ENGINEERING CHANGE NOTICE DART AEROSPACE LTD

··				Licolo		1111	—
Date: 12.05.25 Job No.:			ADR Yes/No: N	ADR Date:	11.	ECN#: 12- 58	87
Product No.: D412-702			Created By: RP	Approved By	WY -		
Product Name: Shoulder Harness			Checked By:	<u> </u>			لــــــ
			Distribution	Reqd	Resp	Initial / Date	\neg
Distribution Reqd Resp	Initial / Date		Distribution DQA / QA Coord.	N	Resp	tintat i bato	\dashv
Production Manager / Coord. Y LUMP				N			\dashv
Purchasing Coord. Y CL			QC Coordinator				\dashv
Production Engineering Coord. Y JL		<u> </u>	Customer Technical Su	pport N			-
	W		Marketing		_		\dashv
			Customer Order Proces	ssing	<u> </u>		
	Data Adicator in :		ientation. Shoulder Strap A	Adjusters positione	d too high.		\neg
Reason for Change: Lap Belts too short. Lap	Beit Adjuster in	wrong or	ieritation. Shoulder Strap /	Adjustero positione	a 150 mg		
Documents Affected:							
Documents Affected.							
DSC-D4305 Rev. B							
103C-04303 Rev. B		1.7					
				•			
					F	7	
PARTS MUST CO	MPLY	X	PREVIOUS PARTS	SATISFACTOR	KY L		
				Netes		Complete	
# Quality Assurance Actions	Reqd	Resp		Notes		Complete	
1 Notify Previous Customers	N						
2 Notify Eurocopter France	N						
						<u> </u>	
3		<u> </u>	<u> </u>				
# Engineering Actions	Reqd	Resp		Notes		Complete	
4 Required Documents/Drawings Under Review	N						
5 Update Master Document List (MDL)	N						
6 Update Product Compatability Matrix	N	T					
7 Create Eurocopter Form (FEE)	N						
8 Notify TC / FAA of Change	N						
9							
						Complete	
# Document Control Actions	Reqd	Resp		Notes		V2. 05.285	₩
10 Move Electronic Files/Design Journal	Y	KJ	<u> </u>			12.03.20	7
11 Update Product Specification Files	N					12.05, 28	Ť
12 Update Approved/Preliminary Dwg PDF Files	Y	KJ	<u> </u>			12.00(20	7/
13 Update Document Record (DR)	N	<u> </u>					
14 Update Product Development Summary	N_		<u></u>				
15 Update QSI 021 and/or STC Approval List	N	1					
16 Update Parts / STC Database	Y	_					
17 Update / Verify ARC Database	Y	L				12.05,28	L
18 Create / Update Change Record Form / Item Card D		KJ				12.05.20	
19 Create / Update PPP's	Y	KJ					
20 Red Decals required?	Y	KJ		·			
21 Update Document Control Database / Laminated Dw		 					
22 Update Grey Project / Electronic Binder PDF Files	N	 				12.05,280	\
23 Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ				12.00.20	7
24		//		· · · · · · · · · · · · · · · · · · ·			
	H = (1)	100	4 / ^		7		
Description / Action:	10 - 1		polife Aurszfe	PIKI DIA	mh	۸ ۱)
	<i>r</i>	u	house buissed	- 17.00 - per	,	AUV	1
AmSafe to produce qty 3 D4305-1 Lap Belts and qty 3 D	4305-3 Lap Beits	5 .		•	(1 D WILLIA	
Parts to be inspected per D4305 Rev B and shipped to H	lillcrest.				1. 10	3 40	
					_VIIV	· Jau	
AmSafe to produce one complete harness assembly to b	e sent to Eagle t	or reviev	<i>I</i> .	100	200.	1 dale "	
			. 50140 505	110		YMI . T	\ \ \
MDL and any other related documents to be updated and	d released at a la	iter date	via ECN12-595		CIC	1. at)
	1			,	$\setminus \nu$	y. V.	
	•				:	-	
All DSC-D4305 in stock to be shipped back to AmSafe for	or rework.	1	`				
All DSC-D4305 in stock to be shipped back to AmSafe for	or rework.	5121	· ·/			11.72	
All DSC-D4305 in stock to be shipped back to AmSafe for D412-702-071 now @ CHG002	or rework.	Spe				12.06.27	•
· ·	or rework.	Spo				to Olth Laged by anit	•

ECN Verified & Complete:

Linda Lacelle

From:

Sian Willems <swillems@dartaero.com>

Sent:

June-26-12 3:04 PM

To:

'Linda Lacelle'; 'Bill Beckett'

Cc:

'David Shepherd'; 'Mike Petsche'; 'Roger Pilon'

Subject:

RE: old crew shoulder harnesses.

Hi Linda,

Rewebbing will cost us about \$380 per seating position.

I would suggest we hold onto old stock but put it in quarantine until we have new stock once the D4305 dwg is released. In a pinch we could provide these to any customers who can't wait for the new design belts to come it. Doe that make sense?

Thanks,

Siân Willems

Customer Support

T: 1-613-632-5200 ext 239

F: 1-613-632-5246 C: 1-613-676-0577 swillems@dartaero.com



Product Documentation: Verify Revision Status/Download HERE

From: Linda Lacelle [mailto:llacelle@dartaero.com]

Sent: June 26, 2012 1:14 PM **To:** 'Sian Willems'; 'Bill Beckett'

Cc: 'David Shepherd'; 'Mike Petsche'; 'Roger Pilon'

Subject: RE: old crew shoulder harnesses.

Still holding on to this ECN 12-587...do we have the existing stock reworked or not pls?

LL

From: Sian Willems [mailto:swillems@dartaero.com]

Sent: May-28-12 9:16 AM

To: 'Bill Beckett'

Cc: <u>llacelle@dartaero.com</u>; David Shepherd; 'Mike Petsche'; Roger Pilon

Subject: old crew shoulder harnesses.

We have We have 3 D412-702-071 crew shoulder harnesses in stock, valued at about \$1,600.

Any new belts ordered will have the longer lap belt, lap adjusters moved, longer shoulder harnesses (to ensure no tension on the belt when sitting back in the seat) and a shorter cable.

I think we should exhaust existing stock and just ensure we sell to customers without the comfort seat (or without obese pilots).

Or I can ask about the cost of rewebbing these belts (probably about \$200 per kit plus freight costs to and from).

Any objections to exhausting existing stock?

Thanks,

Siân Willems
Customer Support

T: 1-613-632-5200 ext 239

F: 1-613-632-5246 C: 1-613-676-0577 swillems@dartaero.com



Product Documentation: Verify Revision Status/Download HERE

List Lots

June-27-12 8:39:57 AM

Page 1 of 1

Item ID Item Name	Warehouse ID Location ID	Lot Number	Last Trans Date	Lot Qty	Shelf Life Dt Lot Code	Type Code	Comments
D4305-041 Shoulder Harness Assembly	Main Warehouse ST272A	69330	2/22/12	2.0000	QC21		
			Total:	2.0000			

List Lots

June-27-12 8:40:06 AM

Page 1 of 1

Item ID Item Name	Warehouse ID Location ID	Lot Number	Last Trans Date	Lot Qty	Shelf Life Dt Lot Code	Type Code	Comments
0412-702-071 i!ot/Co-pilot Shoulder farness, 4 point	Main Warehouse FG051	77701	6/01/12	2.0000	QC21	CHG001	